

Configuration summary

Mat. no.	Description Order code	Quantity	Unit
52017196	Cerabar S PMC71 PMC71-AAA1F11GAAA	1	ST

010	Approval:	A	Non-hazardous area
020	Output; Operating:	A	4-20mA HART; extern + LCD
030	Housing; Cover Sealing; Cable Entry:	A	T14 Alu IP66/67 NEMA6P; EPDM; M20 gland, T14 = side cover (Ex d > M20 thread)
040	Sensor Range; Sensor Overload Limit:	1F	400mbar/40kPa/6psi gauge; 8bar/800kPa/116psi
050	Calibration; Unit:	1	Sensor range; mbar/bar
070	Process Connection:	1G	Thread ISO228 G1-1/2, 316L, flush mount
080	Seal:	A	FKM Viton
100	Additional Option 1:	A	Not selected
110	Additional Option 2:	A	Not selected